

## United States Department of the Interior



BUREAU OF LAND MANAGEMENT Moab District San Rafael Resource Area 900 North 700 East Price, Utah 84501

3809 UTU-69856 (U-067)

APR 2 9 1993

Holland Shepherd
Division of Oil, Gas and Mining
355 West North Temple Street
3 Triad Center
Salt Lake City, Utah 84180-1203

Dear Mr. Shepherd:

A review of our records shows that Tom Clark has not conducted operations on his Daddy Dearest Claim group since 1989. Field inspections show that facilities located on the site are beginning to deteriorate due to lack of maintenance. We recommend that the facilities be removed, the portal sealed, and all surface disturbances be reclaimed. We have had difficulties in getting Mr. Clark to respond to our inquiries, including a letter dated March 11, 1993. Any assistance you can render in getting this problem resolved would be appreciated.

Sincerely,

Area Manager

Smalley

cc: Bryant Anderson, Emery County